


Hooper Bay Airport

Pavement Condition Index - PCI Measured Values for the Year 2002



Airport Code: HPB
Site No.: 50322.*A

[] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60



PCI Values		General Pavement Recommendations
<div></div>	85 - 100	Preventative Maintenance
<div></div>	70 - 84	Preventative / Corrective Maintenance
<div></div>	60 - 69	Corrective Maintenance / Overlay
<div></div>	55 - 59	Overlay / Rehabilitate
<div></div>	40 - 54	Rehabilitate
<div></div>	25 - 39	Reconstruct
<div></div>	10 - 24	Reconstruct
<div></div>	0 - 9	Reconstruct




Hooper Bay Airport

Pavement Condition Index - PCI Predicted Values for the Year 2003



Airport Code: HPB
Site No.: 50322.*A

[] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60



PCI Values		General Pavement Recommendations
<div></div>	85 - 100	Preventative Maintenance
<div></div>	70 - 84	Preventative / Corrective Maintenance
<div></div>	60 - 69	Corrective Maintenance / Overlay
<div></div>	55 - 59	Overlay / Rehabilitate
<div></div>	40 - 54	Rehabilitate
<div></div>	25 - 39	Reconstruct
<div></div>	10 - 24	Reconstruct
<div></div>	0 - 9	Reconstruct




Hooper Bay Airport

Pavement Condition Index - PCI Predicted Values for the Year 2004



Airport Code: HPB
Site No.: 50322.*A

[] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60



PCI Values		General Pavement Recommendations
<div></div>	85 - 100	Preventative Maintenance
<div></div>	70 - 84	Preventative / Corrective Maintenance
<div></div>	60 - 69	Corrective Maintenance / Overlay
<div></div>	55 - 59	Overlay / Rehabilitate
<div></div>	40 - 54	Rehabilitate
<div></div>	25 - 39	Reconstruct
<div></div>	10 - 24	Reconstruct
<div></div>	0 - 9	Reconstruct




Hooper Bay Airport

Pavement Condition Index - PCI Predicted Values for the Year 2005



Airport Code: HPB
Site No.: 50322.*A

[] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60



PCI Values		General Pavement Recommendations
<div></div>	85 - 100	Preventative Maintenance
<div></div>	70 - 84	Preventative / Corrective Maintenance
<div></div>	60 - 69	Corrective Maintenance / Overlay
<div></div>	55 - 59	Overlay / Rehabilitate
<div></div>	40 - 54	Rehabilitate
<div></div>	25 - 39	Reconstruct
<div></div>	10 - 24	Reconstruct
<div></div>	0 - 9	Reconstruct




Hooper Bay Airport

Pavement Condition Index - PCI Predicted Values for the Year 2006



Airport Code: HPB
Site No.: 50322.*A

[] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60



PCI Values		General Pavement Recommendations
<div></div>	85 - 100	Preventative Maintenance
<div></div>	70 - 84	Preventative / Corrective Maintenance
<div></div>	60 - 69	Corrective Maintenance / Overlay
<div></div>	55 - 59	Overlay / Rehabilitate
<div></div>	40 - 54	Rehabilitate
<div></div>	25 - 39	Reconstruct
<div></div>	10 - 24	Reconstruct
<div></div>	0 - 9	Reconstruct




Hooper Bay Airport

Pavement Condition Index - PCI Predicted Values for the Year 2007



Airport Code: HPB
Site No.: 50322.*A

[] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60



PCI Values		General Pavement Recommendations
<div></div>	85 - 100	Preventative Maintenance
<div></div>	70 - 84	Preventative / Corrective Maintenance
<div></div>	60 - 69	Corrective Maintenance / Overlay
<div></div>	55 - 59	Overlay / Rehabilitate
<div></div>	40 - 54	Rehabilitate
<div></div>	25 - 39	Reconstruct
<div></div>	10 - 24	Reconstruct
<div></div>	0 - 9	Reconstruct




Hooper Bay Airport

Pavement Condition Index - PCI Predicted Values for the Year 2008

Airport Code: HPB
Site No.: 50322.*A

[] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60



PCI Values		General Pavement Recommendations
<div></div>	85 - 100	Preventative Maintenance
<div></div>	70 - 84	Preventative / Corrective Maintenance
<div></div>	60 - 69	Corrective Maintenance / Overlay
<div></div>	55 - 59	Overlay / Rehabilitate
<div></div>	40 - 54	Rehabilitate
<div></div>	25 - 39	Reconstruct
<div></div>	10 - 24	Reconstruct
<div></div>	0 - 9	Reconstruct

